

VISUAL TANK INSPECTION REPORT

Vessel :
Port/Terminal:
Product/Cargo:

ETT-112

N. BUTANOL

HERCULES/FREEPORT, TX

Your Reference:

Our Reference: FP/96-2634
Date: 12-10-96

 Tank
 Number
 1C
 2C
 3C

 Tank
 3C
 3C

Coating MILD STEEL MILD STEEL MILD STEEL MILD STEEL
Last

Cargo CYCLOHEXANE CYCLOHEXANE CYCLOHEXANE

Cargo CYCLOHEXANE CYCLOHEXANE CYCLOHEXANE

Cargo CYCLOHEXANE CYCLOHEXANE CYCLOHEXANE CYCLOHEXANE

Accepted * ACCEPTED ACCEPTED ACCEPTED ACCEPTED

Visual Cleanliness

Rejected *
Time/Date

Inspected 1010 / 12-10-96

1010 / 12-10-96

1010 / 12-10-96

Method said to have been used to clean tanks: <u>ALL CARGO TANKS AND PIPELINES WERE STRIPPED AND BLOWN WITH AIR FOR ONE HOUR</u>
EACH

Information regarding previous cargoes, tank coating and cleaning method was obtained from vessel personnel and cannot be guaranteed as accurate by Caleb Brett U.S.A., Inc. and no liability can be assumed for errors resulting from improper information supplied. This report, of necessity, is based on such information.

* The cleanliness of inspected tank(s) is/are based on visual inspection of tank surfaces and line system at accessible areas only. This document does not cover the cleanliness of tank surfaces and line system at inaccessible spots and/or possible release of components of previous cargoes during loading, discharge or transport of the cargo in question, for which the vessel is fully responsible. Suitability of tank coating for intended cargo must be guaranteed by vessel's owner or by suppliers of the coating.

I T S-Caleb Brett